


25 METER ZEROING TARGET FOR M16A1 RIFLE (WITH STANDARD SIGHTS)



1. AIM AT TARGET CENTER. ADJUST SIGHTS TO MOVE SHOT GROUP CENTER AS CLOSE AS POSSIBLE TO WHITE DOT.
2. AT COMPLETION OF ZERO, ROTATE REAR SIGHT TO UNMARKED APERTURE AND WEAPON WILL BE BATTLESIGHT ZERO FOR 250 M.